


Made by professionals...




...For professionals


TECHNICAL DATA

	AROMASTER II	AROSPOT-F5
Transformer	3 phase DC	Single phase AC
Supply voltage	208 - 230 V / 60 Hz	208 - 230 V / 60 Hz
Transformer class	H (180° C)	H (180° C)
Nominal power	30 kVA	18 kVA
Maximum current in short circuit	12,2 kA	9,8 kA
Maximum welding current (RMS)	7,7 kA	5,5 kA
Welding cable length	10 or 16 Ft	6,6 Ft
Thermal protection	Yes	Yes
GLCI	20 mA / 30 ms	20 mA / 30 ms
Electrode force at 6 bars	270 lb	270 lb
Full load amps	60 A	50 A
Supply cable for 30 ft	3 x 6 ga. + gnd	3 x 8 ga. + gnd
Fuses	40 A (delayed)	40 A (delayed)
Dimensions W x D x H	23" x 27" x 40"	13" x 26" x 40"
Total weight (with accessories)	421 lb	253 lb


A VERSATILE EQUIPMENT




◆ Spot welding




◆ Stud welding




◆ Dent pulling




◆ Washer welding



◆ Seam welding



◆ Nut welding



◆ Large dent pulling

